Soil Slope Instability and Stabilisation

Edited by BRUCE F.WALKER Jeffery and Katauskas Pty Ltd, Sydney

ROBIN FELL University of New South Wales, Sydney





Contents

Preface	VII
1 Landslide classification, geomorphology, and site investigations Bruce F.Walker, Russell J.Blong & J.Patrick MacGregor	Contractor 1
2 Determination of drained shear strength for slope stability analysis Robin Fell & Rod P.Jeffery	53
3 Methods of stability analysis Garry R.Mostyn & John C.Small	71
4 Groundwater prediction and control, and negative pore water pressure effect Bruce F.Walker & Frank J.Mohen	ets 121
5 Slope stabilization techniques and their application Andrew R.Leventhal & Garry R.Mostyn	183
6 Slope instability in soft ground Robin Fell, Patrick K.Wong & Peter Stone	231
Case histories	
The treatment and monitoring of unstable rock wedges during excavation of B Power Station J.C.Braybrooke	Bendeela 281
Urban slope stability in the Warringah Shire of Sydney Peter J.Burgess	289
Practical aspects of probabilistic studies for slopes Robin Chowdhury	299
Slip failure in Ashfield Shale at Artarmon, Sydney D.J.Douglas, A.P.Maconochie & B.K.McMahon	305
Hue Hue Road landslide, Wyong Robin Fell, J.Patrick MacGregor, J.Williams & P.Searle	315
The Speers Point landslides Robin Fell, T.D.Sullivan & C.Parker	325

Port Kembla multipurpose berth estimation of undrained strength Robin Fell & C.P.Thorne	333
The Carisbrooke Avenue landslide K.Forrester	337
A case study of subsurface drains at Rogans Hill Rod P. Jeffery	347
Removal of soft tailings by mud displacement techniques <i>A.B.Love</i>	353
Cliff line collapse associated with mining activities <i>P.J.N.Pells</i> , <i>J.C.Braybrooke</i> , <i>G.P.Kotze & J.Mong</i>	359
Garden Island Car Park slope stabilisation works A.B.Phillips	387
Monitored failure of an excavation in an ancient landslide within the Newcastle coal measures $RJ.Rigby \& RJ.Carr$	397
Investigation of the stability of tailings embankment on soft clay K.D.Seddon & K.Chan	403
Monitoring of planar slope failure in rockfill quarry, Glenbawn Dam Peter L.Volk	411
Slope instability in the Coledale area of the Illawarra Escarpment Bruce F.Walker, Bob Amaral & J.Patrick MacGregor	417
Wharf Road foreshore redevelopment, Newcastle Harbour T.J.Wiesner & R.J.Carr	431
Subject index	437